





Hollow Section Steel (HSS) Defective Weld Examples










Typical HSS seam weld face with no visible defects.



Typical HSS seam weld root with no visible defects.